Spinelli Lexus Lachine



Date :

210 boul. Montreal-Toronto Montreal H8S 1B8

1 581 703-8568

Make / Model Audi A6 Technik SLINE BAS KM ... Mileage indicated / actual* 2019 60,773 km **Transmission Drive Type** automatic **AWD Engine Fuel Type** 6 cyl. / 3 liters Serial number Stock number L3687



EQUIPMENTS

SALE PRICE

Air conditioning, Cruise control, Heated Driver Seat, Heated mirrors, Memory seats, Power locks, Power Mirrors, Power driver seat, Power sliding doors, Power steering, Power windows, Remote Entry, Reverse park assist, Dual zone A/C, ABS Brakes, Driver airbag, Fog lights, Passenger airbag, Lateral airbags, Traction control, Rain sensor wipers, Tinted windows, Sunroof, AM/FM stereo, Bluetooth, MP3 Player, Split folding rear seats, Stow'n Go, Tachometer, Reverse camera, Climate control, Leather seats, Split bench seat, Tire pressure monitoring system, Onboard computer, Keyless start, Audio steering controls, USB Port, Automatic wipers

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

	Category	
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:	
Legal warranty : C - 1 month - 1700 KM		
	A 6 months or B 3 months 10 000 km B 5 000 km	s or C 1 month or 1 700 km
	D Good working (subject to 37, 38 L.P.C.)	E No warranty
Repairs done and mechanical verification certificate		Comments
The following repairs have been done on this vehicle since the dealer's possession.		
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.		
Optional repairs		
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below:		

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #:

8255268